

Gunther Todd

From: Kawamoto Gerald
Sent: Wednesday, November 17, 2021 12:52 PM
To: Gunther Todd
Cc: Babcock Christopher
Subject: ERA21LA183 (Weyers Cave, Virginia) Global Positioning System Device Email Report
Attachments: IMG_3375.jpg

Email Report Instructions:

The narrative and attachments from this email report may be used in other reports at the discretion of the IIC. This email, including attachments (if applicable), should also be placed in the docket by the IIC.

Email Report:

The Vehicle Recorder Division received the following device: Dual Electronics XGPS 190 S/N 0002781. The device arrived exhibiting minor impact damage (IMG_3375.jpg). The manufacturer of the device indicated that this model does not contain non-volatile memory, thus no data were recovered.

Prepared by:

Gerald Kawamoto, Recorder Specialist NTSB RE-40

Align arrows with aircraft roll axis.
This side down.
Install straight and level,
away from ferrous metal.



Model XGPS190
ADS-B Receiver
with AHRS

DUAL Electronics Corp.
Heathrow, FL 32746
www.dualav.com



Made in Korea

FCC ID: GJW-XGPS170
IC: 4038A-XGPS170

S/N.: NSD 0 0 0 2 7 8 1

CAUTION: This unit warms up when
operating, and can become hot when
sitting in direct sunlight. Please use care
when handling this unit if it will be used
in a hot environment.

E

WINiZEN

W8E-CO-09

Ver.C

