



MEMORANDUM FOR RECORD

Timothy W. Monville
Sr. Air Safety Investigator
Eastern Region

Date: March 13, 2023
NTSB Accident Number: ERA21LA201

Medical and Pathological Information:

A postmortem examination of the certified flight instructor was not performed; only an external examination was performed by the District 13 Medical Examiner's Office, Tampa, Florida. The cause of death was listed as Sequelae of 85% Body Surface Burns.

Hospital admittance specimens (if any) were not requested for testing from the pilot undergoing instruction or for the certified flight instructor. Additionally, toxicology testing was not performed as part of the external examination for the certified flight instructor.