



Douglass Brazy
Air Safety Investigator
Eastern Region Aviation

June 22, 2021

Subject: NTSB investigation ERA21LA244, N7776S, Schweizer SGS 2-33A, June 5, 2021, Sanford Seacoast Regional Airport (SFM), Sanford, Maine.
Information provided by FAA Inspector

On June 22, 2021, Mr. Mathew Hall, FAA Inspector from the Portland, Maine Flight Standards District Office, provided the following information via email:

The right side of the aft fuselage was bent inward just aft of the wing's trailing edge. A fuselage stringer was bent inward about 30°. The right wing was buckled about mid span, chordwise, forward of the inboard edge of the right aileron. The right aileron was bent at its inboard edge.

<end>