



MEMORANDUM FOR RECORD

Aaron McCarter
Air Safety Investigator
Eastern Region

Date: February 4, 2022
Person: Ronald L Garrison: Pilot/Owner/Builder
NTSB Accident Number: ERA21LA247 Cumberland, MD
Subject: NTSB Form 6120.1

Narrative:

Mr. Garrison was the non-certificated pilot and builder of N315SV involved in the accident cited above. He did not submit an NTSB Form 6120.1

When contacted by telephone, Mr. Garrison provided airplane records, photographs and provided the information needed over the telephone. His written statement, and the statement provided to the NTSB Investigator in Charge was sufficient.

[END]