



Photo 1 – View of powerline pole showing wires coming off right side of pole. (Courtesy of FAA)



Photo 2 – Closeup view of wire with a pen for comparison. (Courtesy of FAA)



Photo 3 – View of overall helicopter damage showing separated tail rotor and blade damage. (Courtesy of FAA)



Photo 4 – Right side of helicopter closeup of damage to rotor mast and fuselage. (Courtesy of FAA)