



MEMORANDUM FOR RECORD

Eric Alleyne
Air Safety Investigator
National Transportation Safety Board
Office of Aviation Safety - Eastern
Region

NTSB Case Number: ERA21LA305

Aircraft: Amateur built, Twin, N327TT

Pilot/mechanic: Tim Tucker

Date: 9/29/2021

**Subject: Engine examination
discussion**

The information below is an email message with discussion that was sent to the NTSB investigator from the Owner /pilot/mechanic of N327TT, regarding the findings during the engine examination.

"Hello Eric.

We were not able to determine the case of failure due to the fuel lines being destroyed in the accident."

In a telephone conversation with Mr. Tucker, he stated that due to the external damage on the engine he was not able to find the source of the brief power loss. He said the since fuel lines were destroyed and he was unable to run the engine.