



NATIONAL TRANSPORTATION SAFETY BOARD

Eastern Region – Ashburn, Virginia

Summary of Email

Who: John Bartley, Somerset Air Service

When: August 11, 2021

The following is an excerpt of an email provided by Mr. Bartley regarding the investigation involving N52MM. He stated:

"We had the plane in the shop yesterday and the landing gear horn works fine and we did several satisfactory retraction tests. The plane will need a new propeller and an engine tear down inspection."

Regards,

John Bartley