



Photo 1 – Front View of Main Wreckage – Courtesy of FAA



Photo 2 -Right Side of Main Wreckage – Courtesy of FAA



Photo 3 – Right Wing – Courtesy of FAA



Photo 4 – Aft Fuselage – Courtesy of FAA



Photo 5 – Empennage and Left Wing – Courtesy of FAA



Photo 6 – Left Side View of Main Wreckage – Courtesy of FAA



Photo 7 – Missing Light and Lense – Courtesy of Piper Aircraft



Photo 8 – Pitch Trim Handle – Courtesy of Piper Aircraft



Photo 9 – Front Seats – Courtesy of Piper Aircraft



Photo 10 – Underside of Seat – Courtesy of Piper Aircraft



Photo 11 - High Expansion Foam



Photo 12 – Fuel Selector



Photo 13 – Close Up of Fuel Selector



Photo 14 – Screw Interfering with Fuel Selector Handle



Photo 15 – Missing Spring Loaded Metal Stop



Photo 16 – Fuel Selector Valve Cover Mounted Off Center and not Clocked / Indexed