

Right wing Tail had pins
Plat started the normally
Gone under suspension.
 $\frac{1}{4}$ quarter ~~away~~ the
had $\frac{1}{4}$ - $\frac{1}{2}$ feet
Both tanks feed D
No mixture Cont

YEAR	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations
20 DATE				Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)

— Texas Rotax & Light Sport Aircraft
— 29890 Bulverde Ln #14, Bulverde, TX 78163
— Phone: (830)-560-9061

Reg # N101KL
Make Just Aircraft
Model JA 20 Highlander
S/N : JA536-11-18
Tach Time 81.8

— Airframe Log Entry- Annual/150 hr Conditional

— Performed airframe Inspection IAW Highlander Model JA 20 Tail Wheel POH 150 hr/Annual
— Inspection pages 24 – 26. Performed Dynon back-up battery test, OK. Fabricated and installed
— external power cable from battery to stow in the rear of pilot's seat. According to owners direction,
— repaired small pin hole fuel leak along aft edge of left fuel tank with JB Weld. Fixed fuel leak at Curtis
— drain valve fitting under vertical header tank. Removed and cleaned Aero Filter element under copilot
— seat. Determined Dynon SB 050620 does not apply to this installation. ELT system checked and
— battery dates recorded per FAR 91.207. This Airframe is Approved for Return to Service after a test
— flight by a qualified pilot and a log entry returning this aircraft to Service. -----END-----

Paul Whetstone [REDACTED] RFSC#30001200322-3835
Date: 08/18/2020

YEAR 20____ DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Repair Facility. (See back pages for other specific entries.)
------------------------	---------------------------	-------------------	-----------------------------	--

N# 101KL S/N 7453611-18 AC Model Highlander
I certify that the Transponder system and integrated
system tests required by FAR 91.413 have been
performed in accordance with FAR 43 Appendix F.
#1 XPNDR PN: TT22 S/N 7960
#2 XPNDR PN: [REDACTED] S/N N/A
Signature: [REDACTED]
Date 8/12/2020 WO# 1278 ACTT Mich 80.8
Certificate No.: CRS# T6ER555Y
Time Aerospace LLC

[illegible]