

----- Forwarded Message -----

From: Terry Hilderbrand [REDACTED]

To: [REDACTED]

Sent: Monday, April 19, 2021, 02:56:42 PM MDT

Subject: 797RT

Ricky Flores
[REDACTED]

This is my statement as to the incident which occurred at KOPN airport in Georgia.

I had purchased this airplane earlier this month and needed someone to ferry this from Vidalia Georgia to Sidney Ne.

Spencer had been recommended to me as a possible solution, so after contacting him and setting up the logistics, we

met in Vidalia and discussed our plan of action. This plane only has brakes on the left side, so I was in the right seat.

Greater fuel usage was noticed than we expected so we decided to land earlier than our planned stop. Winds were not a

factor and approach was good, but as the airplane touched down it went left and veered off the runway. I thought we

Missed everything but after inspection we saw the empennage was damaged and a taxiway sign had minimal

damage only. As I am only a low time student pilot I cannot ascertain to the cause of the controllability of this aircraft.

Terry Hilderbrand
[REDACTED]