Photo 1 – View of lower tail section of airplane showing structural damage.