



Photo 1 – FAA Digital Photograph. Left Side View of the Airplane at the Accident Site. Note the Substantial Damage to the Fuselage.



Photo 2 - FAA Digital Photograph. Right Side View of the Aft Empennage. Note the Substantial Damage to the Right Horizontal Stabilizer.



Photo 3 – Textron Aviation Digital Photograph. Front View of the Left Wing and Aft Empennage Separated For Recovery. Note the Substantial Damage to the Left Wing.