



NTSB MEMORANDUM OF RECORD

Aaron McCarter
Air Safety Investigator
Eastern Region, Office of Aviation Safety (AS-ERA)
National Transportation Safety Board

Date: November 26, 2021
NTSB Accident Number: ERA22FA076
Medical and Pathological Information

According to the autopsy report prepared by the Office of the County Coroner, Mercer County, State of Pennsylvania, the cause of death for the pilot was the result of thermal effect and fire exposure.

According to toxicology testing performed by the FAA's Forensic Sciences Laboratory, Ethanol, drugs of abuse, and carboxyhemoglobin were not detected in the pilot. No medications were found that would have posed a hazard to flight safety or likely would have contributed to the accident.

No autopsy or toxicology testing was conducted on the pilot rated passenger who succumbed to his injuries the day after the accident.