

NTSB Investigation: ERA22FA083 | N5776B (Cessna 182)


Maintenance Records Excerpts

Page No. _____

Date	Total Time	DESCRIPTION OF WORK PERFORMED SIGNATURE & CERTIFICATE NUMBER OF PERSON PERFORMING WORK
CARRIED FORWARD →		
	FERNANDINA BEACH AIRCRAFT MAINTENANCE	10/15/2021
	[REDACTED]	
	N5776B CESSNA 182 S/N 33776 TACH: 403.6 TT: 9226.4	
	PERFORMED AN ANNUAL INSPECTION PER FERNANDINA BEACH AIRCRAFT MAINTENANCE INSPECTION SHEET. C/W AD 11-10-09 SEAT RAILS AND SEATS BY INSPECTION NEXT DUE 503.6 OR 10/2022. CW AD 76-07-12R1 IGNITION SWITCH BY OPERATIONAL CHECK. NEXT DUE 503.6. C/W AD 83-10-01 FUEL CAP SEA;ING BY INSPECTION. NEXT DUE 503.6. CW AD 84-10-01R1 WATER IN FUEL TANK BY INSPECTION. NEXT DUE 10/2022. REPLACED RIGHT OUTBAORD BRAKE LINING 1ea 66-10500. THIS AIRCARFT HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND HAS BEEN FOUND AIRWORTHY. THE END	
	WO 832 SHERMAN R KELLER,	[REDACTED] IA [REDACTED]

Engine Overhaul


SERVICE	OVERHAUL	TIME
TOTALS brought forward from previous page		

ZEPHYR AIRCRAFT ENGINES INC.


W.O. No. 220130 N5776B Dated: August 11, 2020
Mfg. Continental Model: IO-520-F / O-470-50
Serial No. 570858 P.Ponk S/N.2482 Engine Total Time. _____
Time since Major Overhaul. 0.00

This is to certify that the engine described hereafter has been overhauled to manufacturer's new parts

Limits. The Engine was disassembled, cleaned, and inspected in accordance with Manufacturer's instructions. All steel parts magnafluxed, reassembled and test run in accordance with manufacturer's current overhaul manual and in accordance with current Federal Aviation Regulations and is approved for return to service. Pertinent details of these repairs are on file at this agency under the W.O.220130 listed above. All applicable Airworthiness Directives thru 2020-16 are in compliance. See A.D. list supplied.

F.A.A. APPROVED REPAIR STATION #VI4R397M 
Authorized Signature
Herman Vollrath

Engine IO-520-F previously modified per P.Ponk STC SE4988NM to a O-470-50 S/N. 2482

Components, Accessories, & Related Parts supplied or installed.				Overhauled	Repaired	Not Repaired
Carburetor	P/N	10-4893-1	S/N	H172337R	X	
Left Magneto	P/N	6310	S/N	20060426	NEW	
Electronic Module	P/N	SIM6C	S/N	6C-1720004	NEW	
Starter Motor	P/N	C12ST4	S/N	H-U040651	NEW	
Oil Cooler	P/N	626371	S/N	041	X	
Ignition Harness	P/N	M2381 (NEW)				
Spark Plugs	P/N	RHB32E (NEW)				

Propeller

AIRCRAFT MAINTENANCE RECORD			Page No. _____
Date	Total Time	DESCRIPTION OF WORK PERFORMED	
CARRIED FORWARD →		SIGNATURE & CERTIFICATE NUMBER OF PERSON PERFORMING WORK	
5/9/21	230.9	Fire rt + left Co-WD Master Doser	moved to Air owner for
FERNANDINA BEACH AIRCRAFT MAINTENANCE		07/01/2021	
N5776B PROP McCAULEY 2A34C66-NP S/N 710353 TACH: 307.4			
PERFORMED AN 100hr INSPECTION AND FOUND PROP TO BE AIRWORTHY			
WO 785 SHERMAN R KELLER		A&P	
FERNANDINA BEACH AIRCRAFT MAINTENANCE		10/15/2021	
N5776B PROP McCAULEY 2A34C66-NP S/N 710353 TACH: 403.6			
PERFORMED AN 100hr INSPECTION AND FOUND PROP TO BE AIRWORTHY			
WO 832 SHERMAN R KELLER		A&P	

© 1995 - 2007 - Idata, Inc. (idata.com)

Prepared by _____