



Memorandum For Record

Timothy W. Monville
Sr. Air Safety Investigator
Eastern Region

Date: 2/29/2024
NTSB Accident Number: ERA22FA126

As part of the investigation, a 3 minutes 0 seconds long video from a tractor trailer that was driving on the highway behind the impacted truck was provided to NTSB. The video with sound from the cab depicted the occupants talking with a view looking forward as the truck proceeded along the highway. At about 1 minutes 30 seconds elapsed time, with several vehicles in all 3 lanes of the highway, the airplane appeared (left side view) to the right of the lanes in a slight nose up attitude (Figure 1). The video did not depict the collision with the truck but there was nothing unusual observed about the left wing or left side of the fuselage. A large fireball covering all 3 lanes began about 1 minute 32 seconds elapsed time and the video depicted vehicles moving to the left to avoid the fire. The truck taking the video stopped behind another tractor trailer and the video depicted the impacted tractor trailer rolling onto its side and coming to rest. The fire continued to the end of the video recording.



Figure 1: Screen Shot From Video Depicting a Left Side View of the Airplane in a Slight Nose-Up Attitude Immediately Before Impact.