



Photo 1 – right wing



Photo 2 – cockpit and instrument panel



Photo 3 - engine



Photo 4 – Left wing



Photo 5 – tail section

NTSB # ERA22FA320

Date 7/18/2022

Accident Location, Basehor, Kansas



Photo 6 – strut and thru bolt (kit manufacturer)