

ERA22FA344

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Main Wreckage



Photograph 2 - Attached Rotor Blade



Photograph 3 - Teeter Head



Photograph 4 - Blade Grip from Missing Rotor Blade



Photograph 5 - Fracture Surface Outboard of Blade Grip from Missing Rotor Blade



Photograph 6 - Engine and PSRU



Photograph 7 - Propeller