

<u>NATIONAL TRANSPORTATION SAFETY BOARD</u>		Time 10:00 am	Date 11/9/2021
RECORD OF: ☐ VISIT ☐ CONFERENCE ☒ TELEPHONE CALL			
Name (s) of Person (s) contacted or in conference and location		Routing	
Mr. Jack Forhbieter-Pilot		Symbol	Initials
Subject: N3940H-Beaver County Airport (BVI)			
Digest: In a telephone interview with Mr. Jack Forhbieter, he stated that during his approach he was distracted by a traffic conflict between two other aircraft. He said that he normally uses his pre-landing checklist but while paying attention to the event he forgot. He said he thought he had an opportunity to catch the problem but was overly concerned with the other aircraft. The airplane landed gear up and slid to a stop on the runway. After exiting the airplane and assistance came, they lifted the airplane and extended the landing gear normally.			
Conclusions, Action Taken, or Required: This correspondence was reviewed with pilot			
Date	Title	Signature	
11/9/2021	ASI	Alleyne	