



Millicent Hill
Aviation Accident Investigator
Office of Aviation Safety

Date: May 4, 2022

Subject: ERA22LA187

Contact: Jeff Edwards, Lancair Owners and Builders Organization

Mr. Edwards stated he was familiar with the LX7 conversion by RDD Enterprises. He was not familiar with any requirements to replace the window after 30 years, they were replaced on condition. Some possibilities that could occur would be, if the window was not installed correctly, or if bonding was not applied correctly, delaminating could occur.