

HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS ☐

Year: _____	Total Time in Service	Description
Date: _____	wo: WO_204	
Next Inspection Due: _____		
	Romanair WDR Inc. [REDACTED]	Winder, GA 30680
Year: _____	N310DC	McCauley, 3AF32C528-A, S/N: 002110
Date: _____	Hobbs: 2012.9	L PROP TSO: 623.1 L PROP TTIS: 1252.7
Next Inspection Due: _____		April 11, 2022
	1. Annual/100 Hour Inspection complied with per McCauley Propeller Manual Chapter 61. Inspected, cleaned and lubricated as required.	
	Annual/100 Hour Inspection complied with per Manufactures Maintenance Manual, Approved Checklist, and FAA Title 14 CFR Part 43 Appendix D. I Certify that this Propeller has been inspected in accordance with an Annual Inspection and was determined to be in Airworthy condition this date.	
	This Propeller is approved for return to service with respect to stated work performed in accordance with Title 14 CFR Part 43.13. Details of work performed are on file with Romanair WDR Inc. under work order: WO_204.	
Year: _____		
Date: _____		
Next Inspection Due: _____	Matt Barnard A&P/IA [REDACTED]	[REDACTED]
	Mech. Cert. # or Repair Station # _____	

HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS ☐

Year: _____	Total Time in Service	Description
Date: _____	wo: WO_204	
Next Inspection Due: _____		
	Romanair WDR Inc. [REDACTED]	Winder, GA 30680
Year: _____	N310DC	McCauley, 3AF32C528-A, S/N: 002112
Date: _____	Hobbs: 2012.9	R PROP TSO: 623.1 R PROP TTIS: 1252.7
Next Inspection Due: _____		April 11, 2022
	1. Annual/100 Hour Inspection complied with per McCauley Propeller Manual Chapter 61. Inspected, cleaned and lubricated as required.	
	2. Propeller removed for repair. Reference Sensenich Propeller Service Inc. CRS# S46R346N FAA Form 8130-3 # 22-0170 dated 01 APR 2022. Installed per McCauley SB227B, Decal A-2230-9.	
	Annual/100 Hour Inspection complied with per Manufactures Maintenance Manual, Approved Checklist, and FAA Title 14 CFR Part 43 Appendix D. I Certify that this Propeller has been inspected in accordance with an Annual Inspection and was determined to be in Airworthy condition this date.	
	This Propeller is approved for return to service with respect to stated work performed in accordance with Title 14 CFR Part 43.13. Details of work performed are on file with Romanair WDR Inc. under work order: WO_204.	
Year: _____		
Date: _____		
Next Inspection Due: _____	Matt Barnard A&P/IA [REDACTED]	[REDACTED]

PROPELLER LOGBOOK