



Ralph E. Hicks
Senior Air Safety Investigator
AS-ERA

Date: 7/14/2022

Subject: ERA22LA282, Torque Tube History

Contact: John Pless, FAA FSDO, ATL

Mr. Pless researched the history of the left main landing gear torque tube. He reported that, according to Mr. Jimmy Garland (S&S Aviation, the maintainer of N414HF), the torque tube was original to the aircraft and had never been replaced.