



MEMORANDUM OF RECORD

Mechanic Correspondence Summary

Lynn Spencer
Air Safety Investigator
Eastern Region Aviation

Date: August 3, 2022

Correspondence from: Kenneth Gohlke, mechanic

Accident Number: ERA22LA298

Narrative:

The following is a summary of an email received from Mr. Gohlke at 1517 EDT on August 3, 2022, in response to questions posed about the wreckage and subsequent examination:

The questions posed were:

1. Was there a smell of fuel at the accident site?
2. Did you note any deformation to the fuel tanks?
3. Could the position of the fuel selector be determined?

Mr. Gohlke's response stated, in part:

Lynn, we did not notice a fuel smell at the crash site. The left-wing fuel tank had no deformations. The right fuel tank was damaged in the crash. The position of the fuel selector valve is difficult to tell since all structure around the actuating arm was twisted.