YEAR: 2022 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
4/15	6490		6490	Performed 100 hr inspection IAW Textron Maintenance Manual for a Skyhawk engine. Also changed oil, replaced oil strainer gasket. This aircraft is DC by return to service. [redacted]

YEAR: 2022 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
4/15	6490		6490	Performed 100 hr inspection IAW Textron Maintenance Manual for a Skyhawk engine. Also changed oil, replaced oil strainer gasket. This aircraft is DC by return to service. [redacted]

YEAR: 2022 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
4/15	6490		6490	I certify that I have inspected this aircraft on [redacted] in accordance with the scope and detail of Appendix D, FAR Part 43 and found it to be in a condition for safe operation. Steven D. Martin, A&P [redacted]