

RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE
---------------------------	-------------------	-----------------------------

Description of Inspections, Tests, Repairs and Alterations

Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)

Carroll, Ohio 43130



Phone Number: [REDACTED]
Date: 5/26/2022

Engine

ENGINE TACH: 7252 TTE: 13725

TSMOH: 1366

N Number: N9556H

Engine Inspection

Engine inspected following scope and detail of FAR 43 Appendix D and manufactures service manual.

Completed the following:

1. Compressions are as follows: 1: 79/80 2: 79/80 3: 68/80 4: 79/80
2. Cleaned and gapped spark plugs.
3. Pressurized exhaust and checked for leaks. None noted.
4. Pressurized primer lines to check for leaks. None noted
5. Drained oil, changed filter and serviced engine with 8 quarts of Phillips 20W50X oil and AA48110-2 filter.
6. Cut filter open and checked for debris. None noted.
7. Carb heat box requires bracket repair. Repaired bracket and riveted back together.
8. Checked mag timing and meggered spark plug wiring.
9. Inspected engine mounts.
10. Checked engine for oil leaks, missing hardware, baffles, and wiring issues.
11. Verified correct operation of all engine controls.

"Maintenance Release"

The aircraft and or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service. Pertinent details of the repair are on file at this agency. Aircraft returned to service.

James A. Shadd A&P [REDACTED] IA