



MEMORANDUM OF RECORD

Lynn Spencer
Air Safety Investigator
Eastern Region Aviation

Date: August 18, 2022
Summary of E-mail from: Allan Greg Pixley
NTSB Accident Number: ERA22LA323

Narrative:

The following is an excerpt from an e-mail received from Mr. Pixley at 0842 EDT on August 18, 2022:

As promised I wanted to get back with you and let you know my external engine, ignition, and carb inspection revealed nothing new or out of order to cause the engine roll back. Due to the condition of the propeller I did not attempt an engine run. Idle setting or carb ice is my best guess.