

NATIONAL TRANSPORTATION SAFETY BOARD

NTSB Form 6120.1

PILOT/OPERATOR AIRCRAFT ACCIDENT/INCIDENT REPORT

Email the pilot/operator aircraft accident/incident report to the investigator-in-charge of your accident/incident. If email is not available, mail the report per the instructions below.

If your accident/incident occurred in Maine, Vermont, New Hampshire, Massachusetts, Connecticut, Rhode Island, New York, New Jersey, Pennsylvania, Maryland, Delaware, Virginia, West Virginia, Kentucky, Tennessee, North Carolina, South Carolina, Mississippi, Alabama, Georgia, Florida, the District of Columbia, Puerto Rico, or the US Virgin Islands, send the form to: NTSB, ERA, 45065 Riverside Parkway, Ashburn, VA 20147.

If your accident/incident occurred in Ohio, Michigan, Indiana, Wisconsin, Illinois, Minnesota, Iowa, Missouri, Arkansas, Louisiana, North Dakota, South Dakota, Nebraska, Kansas, Oklahoma, Texas, Colorado, or New Mexico, send the form to: NTSB, CEN, 4760 Oakland Street, Suite 500, Denver, CO 80239.

If your accident/incident occurred in Montana, Wyoming, Idaho, Utah, Arizona, Nevada, Washington, Oregon, California, Hawaii, or the territories of Guam or American Samoa, send the form to: NTSB, WPR, 505 South 336th Street, Suite 540, Federal Way, WA 98003.

If your accident/incident occurred in Alaska, send the form to: NTSB, ANC, 222 West 7th Avenue, Room 216, Box 11, Anchorage, AK 99513.

Rules pertaining to notification of aircraft accidents and incidents, as well as overdue aircraft are found in 49 *Code of Federal Regulations* (CFR) Part 830 http://www.ecfr.gov/cgi-bin/text-idx?c=ecfr&tpl=/ecfrbrowse/Title49/49cfr830_main_02.tpl. These rules state the authority of the NTSB, define accidents, incidents, injuries, and other terms, and provide procedures for initial and immediate notification of accidents and incidents by aircraft pilots/operators.

A. APPLICABILITY

The pilot/operator of an aircraft shall send a report to the office listed above, based on accident/incident location; immediate notification is required by 49 CFR 830.5(a). **The report shall be filed within 10 days after an accident for which notification is required by Section 830.5, or after 7 days if an overdue aircraft is still missing.**

An aircraft accident, as defined in 49 CFR 830.2, is determined as an occurrence that involves a fatality or serious injury, or substantial damage to the aircraft. For occurrences that do not involve a fatality, the determination that the occurrence is an accident can be appealed by writing to the Director, Office of Aviation Safety, NTSB, 490 L'Enfant Plaza, S.W., Washington, D.C. 20594.

INSTRUCTIONS TO PILOTS/OPERATORS FOR COMPLETING THIS FORM

It is necessary that ALL questions on this report be answered completely and accurately.

If more space is needed, continue on a blank sheet of paper.

Nearest City/Place: Use the name of the nearest community in the state where the accident/incident occurred.

Date Time: Indicate the date and local time of the event. Be sure to indicate the time zone.

Phase of Operation: Indicate the phase of operation during which the accident/incident occurred.

Aircraft Information: Enter aircraft make and model information as indicated on the aircraft registration certificate, including series. If the involved aircraft is certified as "amateur-built," include the name of the producer of the kit or plans, unless an NTSB employee instructs otherwise.

Maximum Gross Weight: Enter the certificated maximum gross weight for the aircraft involved in the occurrence. This should be the same as the maximum gross weight indicated on the aircraft weight and balance documents.

Engine: Enter engine make and model information as indicated on the engine data plate.

The NTSB uses this form for aircraft accident prevention activities and for statistical purposes. NTSB regulations (49 CFR Part 830) require that **ALL** questions be answered completely and accurately. Completion of this form will take approximately 60 minutes. The NTSB does not guarantee the privacy of any information provided in this form. You need not complete this form unless it displays a valid OMB control number, in accordance with 5 C.F.R. § 1320.5(b), which applies to this collection of information.

B. DEFINITIONS

1. "Aircraft Accident" means an occurrence associated with the operation of an aircraft that takes place between the time any person boards the aircraft with the intention of flight and all such persons have disembarked, and in which any person suffers death, or serious injury, or in which the aircraft receives substantial damage. For purposes of this form, the definition of "aircraft accident" includes "unmanned aircraft accident," as defined at 49 CFR 830.2.

2. "Substantial Damage" means damage or failure that adversely affects the structural strength, performance or flight characteristics of the aircraft, and that would normally require major repair or replacement of the affected component. NOTE: Engine failure or damage limited to an engine if only one engine fails or is damaged, bent fairing or cowlings, dented skin, small puncture holes in the skin or fabric, ground damage to rotor or propeller blades, and damage to landing gear, wheels, tires, flaps, engine accessories, brakes, or wing tips are not considered "substantial damage" for purposes of this report.

3. "Operator" means any person who causes or authorizes the operation of an aircraft, such as the owner, lessee, or bailee of an aircraft.

4. "Fatal Injury" means any injury that results in death within thirty (30) days of the accident.

5. "Serious Injury" means any injury that (1) requires hospitalization for more than 48 hours, commencing within 7 days from the date the injury was received; (2) results in a fracture of any bone (except simple fracture of fingers, toes, or nose); (3) causes severe hemorrhages, nerve, muscle, or tendon damage; (4) involves injury to any internal organ; or (5) involves second- or third-degree burns, or any burns affecting more than 5 percent of the body surface.

Type of Fire Extinguishing System: If a fire extinguishing system was used to fight an aircraft fire, specify the type(s) of extinguishing system(s) used. Examples include handheld extinguisher, engine fire bottle, cargo/baggage compartment fire suppression system, or airport emergency ground equipment.

Owner/Operator Information: Enter the owner information as shown on the registration certificate. Commercial operators, enter the operator information, including "doing business as" when applicable, as shown on the operator certificate.

Revenue Sightseeing Flight: Indicate whether the accident aircraft was conducting **revenue** sightseeing operations under 14 CFR Part 91 at the time of the accident.

Air Medical Flight: Indicate whether the accident flight was being conducted for the purpose of carrying medical personnel, patient(s), or organs.

Public Aircraft: Federal, state or local government flight operations such as official travel, law-enforcement, low-level observation, aerial application, firefighting, search and rescue, biological or geological resource management, or aeronautical research. Indicate whether the flight was conducted by the armed forces, federal, state, or local government.

Purpose of Flight: 14 CFR Parts 91, 103, 133, 136, and 137: Indicate the type of operation that was being conducted at the time of the occurrence using the following definitions:

AERIAL APPLICATION--Operations using an aircraft to perform aerial application or dispersion of any substance. Examples include agricultural, health, forestry, cloud seeding, firefighting, insect control, etc.

AERIAL OBSERVATION--These flights include aerial mapping/photography, patrol, search and rescue, hunting, highway traffic advisory, ranching, surveillance, oil and mineral exploration, criminal pursuit, fish spotting, etc.

AIR DROP--Aerial operations, other than aerial application, that are intended to release items in flight.

AIR RACE/SHOW--Includes any flight operations conducted as part of an organized air race or public demonstration.

BUSINESS--includes all personal flying without a paid professional crew for reasons associated with furthering a business, including transportation to and from business meetings or work. This does not include corporate/executive operations, air taxi, or commuter operations.

EXECUTIVE/CORPORATE--Company flying with a paid, professional crew.

FERRY--Non-revenue flight under a special flight or "ferry" permit. Refer to 14 CFR 21.197 for details of special flight permit issuance.

FLIGHT TEST--Flight for the purpose of investigating the flight characteristics of an aircraft/aircraft component or evaluating an applicant for a pilot certificate or rating.

INSTRUCTIONAL--Flying while under the supervision of a flight instructor or receiving air carrier training. Personal proficiency flight operations and personal flight reviews, as required by federal air regulations, are excluded.

OTHER WORK USE--Miscellaneous flight operations conducted for compensation or hire such as construction work (not 14 CFR Part 135 operation), parachuting, aerial advertising, towing gliders, etc.

PERSONAL--Flying for personal reasons (excludes business transportation) including pleasure or personal transportation. This also includes practice or proficiency flights performed under flight instructor supervision and not part of an approved flight training program.

POSITIONING--Non-revenue flight conducted for the primary purpose of relocating the aircraft. Examples include moving the aircraft to a maintenance facility or to load passengers or cargo etc.

UNKNOWN--Use only if the primary purpose of flight is not known.

Other Aircraft--Collision: For all accidents involving a collision with another aircraft, including parked aircraft, check "Collision with other aircraft" under Basic Information and complete this section indicating details about the OTHER aircraft involved in the collision.

Airport Information: Complete this section if the accident/incident occurred on approach, landing, takeoff, departure, or within 3 statute miles of an airport. Please refer to the FAA Airport/Facility Directory or other official source for airport information.

Airport Identifi : Provide the official 3 or 4 character airport identifier number.

Runway: Indicate the number of the runway used, including L, R, or C if applicable.

Runway/Landing Surface: Indicate the type of intended runway/landing surface (do not indicate surface conditions). If the surface type was mixed, check all that apply.

Condition of Runway/Landing Surface: Indicate the condition of the intended runway/landing surface. If multiple conditions existed at the time of the accident, check all that apply.

Weather Information at the Accident/Incident Site: Indicate the weather conditions reported at the accident/incident site at the time of occurrence. If no weather reporting was available for the accident/incident site, indicate the reported conditions at the nearest reporting site. Specify the weather reporting site identifier, the observation time, and distance from the accident/incident.

Sky/Lowest Cloud Condition: Indicate the height above ground level of the lowest cloud condition present at the time of the accident/incident and whether coverage was reported as few, scattered, broken or overcast. Also indicate the height above ground level and coverage of the lowest cloud ceiling present at the time of the accident/incident (reported as broken or overcast).

NOTAMS (D and FDC), AIRMETs, SIGMETs, PIREPs: Describe all NOTAMS (distant (D) or Flight Data Center (FDC), if known), AIRMETs, SIGMETs, and PIREPs in effect near the accident/incident.

Flight Crewmember Information: Indicate the category that best describes the capacity served by this flight crewmember at the time of the accident. The designators "Flight Crewmember 1" and "Flight Crewmember 2" do not refer to a specific pilot position or responsibility. If more than one pilot is aboard, they may be entered in any order and their capacity entered as appropriate.

Degree of Injury: See Definitions on the top half of Page 1 of the instructions. Minor injury is not defined. If an injury does not meet the criteria for another injury category, select Minor.

Date of Last Flight Review or Equivalent: Enter the date of the most recent flight review, or equivalent, completed by this pilot. Refer to 14 CFR 61.56 for accepted equivalents.

Type Ratings: List all type ratings on the pilot certificate. If the pilot holds no type ratings indicate "none." If the pilot holds a pilot certificate other than student and was flying an aircraft requiring an endorsement, enter the type and date of any logbook endorsement(s) for that aircraft. See 14 CFR 61 for examples of required endorsements.

Student Endorsements: If the pilot holds a student pilot certificate, enter all solo endorsements and dates on the student pilot certificate.

Flight Time: Complete the flight time matrix. Solo flight time should be included as "Pilot-in-Command (PIC)" and all dual flight instruction given should be included as "Time as Instructor."

Additional Flight Crewmembers: Complete this section if there were more than two required flight crewmembers on the aircraft. This also includes a check airman performing official duties but does not include cabin crew. State the capacity served by each included crewmember at the time of the accident.

Passenger(s)/Other Personnel: Enter identification and injury severity information for all passengers, cabin crew, and other personnel involved in the accident. See Page 1 of the instructions for the official definition of injury levels.

Several questions throughout the form allow for multiple responses; when appropriate, choose all responses that apply.

These instructions only pertain to major issue areas covered by NTSB Form 6120.1 Pilot/Operator Aircraft Accident/Incident Report. For additional definitions of questions and responses, please refer to www.nts.gov.

NATIONAL TRANSPORTATION SAFETY BOARD PILOT/OPERATOR AIRCRAFT ACCIDENT/INCIDENT REPORT

This form to be used for reporting civil and public aircraft accidents and incidents

BASIC INFORMATION

Accident/Incident Location

Nearest City/Place: Baker State: FL

ZIP: 32531 Country: USA

Latitude: _____ Longitude: _____

(Enter in decimal degrees or degrees:minutes:seconds)

Accident/Incident Date/Time

Date: 07/16/22 Local Time: 0635
mm/dd/yyyy

Time Zone: Central

Collision with Other Aircraft: ☐ Midair ☐ On-ground ☒ None

AIRCRAFT INFORMATION

Registration Number: N347CX

Manufacturer: Allan G. Pixley

Model: Thatcher CX4

Serial Number: 001

Year of Manufacture: 2013

Amateur-Built: ☒ Yes ☐ No If Yes: ☒ Kit/Plans ☐ Original Design Make: Thatcher

☐ IFR-Equipped and Certified

☐ Commercial Space Flight

☐ Unmanned Aircraft

Maximum Gross Weight: 884 lbs

Weight at Time of Accident/Incident: 838 lbs

Number of Seats: 1 Flight Crew Seats: _____

Cabin Crew Seats: _____ Passenger Seats: _____

Number of Engines: 1

Category of Aircraft

- ☒ Airplane
- ☐ Balloon
- ☐ Blimp/Dirigible
- ☐ Glider
- ☐ Gyroplane
- ☐ Helicopter
- ☐ Powered Lift
- ☐ Rocket
- ☐ Ultralight
- ☐ Unknown

Type of Airworthiness Certificate

(Check all that apply)

Standard

- ☐ Normal
- ☐ Aerobatic
- ☐ Balloon
- ☐ Commuter
- ☐ Transport
- ☐ Utility

Special

- ☐ Restricted
- ☐ Limited
- ☐ Provisional
- ☐ Special Flight
- ☒ Experimental
- ☐ Special Light-Sport
- ☐ Experimental Light-Sport

☐ Certificate of Authorization or Waiver (COA)
☐ None ☐ Unknown

Landing Gear

(Check all that apply)

☐ Retractable

- ☐ Tricycle ☒ Tailwheel
- ☐ Amphibian ☐ High Skid
- ☐ Emergency Float ☐ Skid
- ☐ Float ☐ Ski
- ☐ Hull ☐ Ski/Wheel
- ☐ Other Launch/Recovery System
- ☐ None ☐ Unknown

Engine Type (Select one)

- ☒ Reciprocating ☐ Liquid Rocket
- ☐ Turbo Shaft ☐ Solid Rocket
- ☐ Turbo Prop ☐ Hybrid Rocket
- ☐ Turbo Jet ☐ None
- ☐ Turbo Fan ☐ Unknown
- ☐ Electric

Fuel System Type (Reciprocating)

- ☒ Carburetor ☐ Fuel-Injected

Engine	Engine Manufacturer	Engine Model/Series	Manufacturer's Serial Number	Date of Mfg. mm/dd/yyyy	Rated Power ☒ Horsepower or ☐ lbs of Thrust	Total Time (hours)	Time Since: Inspection (hours)	Overhaul (hours)
Eng. 1	Great Planes	Type 1 VW 2180CC	031212-0341EADD	03/12/2012	76	269.2	3	0.7
Eng. 2								
Eng. 3								
Eng. 4								

Last Inspection Type

- ☐ 100-Hour ☐ Continuous Airworthiness
- ☐ AAIP ☒ Conditional Inspection
- ☐ Annual ☐ Unknown

Date Last Inspection: 07/21/2021
mm/dd/yyyy

Airframe Total Time: 269.2 hrs

hours measured at (Select one)

- ☐ Last Inspection ☒ Time of Accident/Incident

Type of Maintenance Program (Select one)

- ☐ Annual
- ☒ Conditional (Amateur-built only)
- ☐ Manufacturer's Inspection Program
- ☐ Other Approved Inspection Program (AAIP)
- ☐ Continuous Airworthiness
- ☐ Other, specify: _____

Description of Fire Extinguishing System

- ☒ None
- ☐ Specify: _____

Propeller 1

- ☒ Fixed Pitch
- ☐ Controllable Pitch
- ☐ Ground Adjustable

Manufacturer: Ed Sterba

Model: Wood

Propeller 2

- ☐ Fixed Pitch
- ☐ Controllable Pitch
- ☐ Ground Adjustable

Manufacturer: _____

Model: _____

ELT Installed: ☐ Yes ☒ No

If Yes:

ELT Manufacturer: _____

Model or Part No.: _____

TSO No.: ☐ OC91 (121.5 MHz) ☐ OC91a (121.5 MHz)
☐ OC126 (406 MHz)

Was ELT still mounted in aircraft? ☐ Yes ☐ No

Was ELT still connected to antenna? ☐ Yes ☐ No

Did ELT Activate? ☐ Yes ☐ No

If activated:

Did ELT Aid in Locating Aircraft? ☐ Yes ☐ No

If not activated:

- Indicate Reason:
- ☐ Impact Damage
 - ☐ Fire Damage
 - ☐ Battery Expired/Damaged
 - ☐ Unknown

Additional Equipment (Check all that apply)

- ☐ ADS-B
- ☐ Airframe Parachute
- ☐ Angle of Attack Indicator
- ☐ Autopilot
- ☐ Data Recorder
- ☐ Electronic Flight Bag or Handheld Device
- ☐ Electronic Multifunction Display
- ☐ Electronic Primary Flight Display
- ☐ Handheld GPS
- ☐ Heads Up Display
- ☐ Onboard Weather
- ☐ Satellite Tracking Device
- ☐ Stall Warning System
- ☐ Video Recording Device
- ☐ Other, Specify: _____

OWNER/OPERATOR INFORMATION			
Registered Aircraft Owner Name: <u>Pixley Allan G</u> Fractional Ownership Aircraft: ☐ Yes ☒ No		City: <u>Niceville</u> State: <u>FL</u> ZIP: <u>32578</u> Country: <u>USA</u>	
Operator of Aircraft ☒ Same As Registered Owner Name: _____ Doing Business As: _____ Air Carrier/Operator Designator (4 Character Code): _____		☒ Same Address as Registered Owner City: _____ State: _____ ZIP: _____ Country: _____	
Operating Certificates Held <i>(Check all that apply)</i> ☒ None ☐ Flag Carrier Operating Certificate (FAR 121) ☐ Supplemental ☐ Air Cargo ☐ Foreign Air Carriers (FAR 129) ☐ Rotorcraft External Load (FAR 133) ☐ Commuter Air Carrier (FAR 135) ☐ On-Demand Air Taxi (FAR 135) ☐ Commercial Air Tour (FAR 136) ☐ Agricultural Aircraft (FAR 137) ☐ Pilot School (FAR 141) ☐ Certificate of Authorization or Waiver (COA) ☐ Commercial Space Transportation Experimental Permit ☐ Commercial Space Transportation License ☐ Other Operator of Large Aircraft	Regulation Flight Conducted Under ☐ FAR 91 ☐ FAR 103 ☐ FAR 121 ☐ FAR 125 ☐ FAR 129 ☐ FAR 133 ☐ FAR 135 ☐ FAR 137 ☐ FAR 415 ☐ FAR 431 ☐ FAR 435 ☐ FAR 437 ☐ FAR 91 Special Flight ☐ Non-US, Commercial ☐ Non-US, Non-commercial ☐ Public Aircraft <i>(Select one)</i> ☐ Armed Forces ☐ Federal ☐ State ☐ Local ☒ Unknown	Revenue Operation for FAR 121, 125, 129, 135 <i>(Select one for each group)</i> ☐ Scheduled or Commuter ☐ Non-Scheduled or Air Taxi ☐ Domestic ☐ International ☐ Passenger ☐ Cargo ☐ Mail Contract Only	
Revenue Sightseeing Flight ☐ Yes ☒ No		Purpose of Flight for FAR 91, 103, 133, 137 <i>(Select one)</i> ☐ Aerial Application ☐ Aerial Observation ☐ Air Drop ☐ Air Race/Show ☐ Banner Tow ☐ Business ☐ Executive/Corporate ☐ External Load ☐ Ferry ☐ Firefighting ☐ Flight Test ☐ Glider Tow ☐ Instructional ☐ Other Work Use ☐ Personal ☐ Positioning ☐ Skydiving ☐ Unknown	
AIRPORT INFORMATION <i>(Fill in if accident/incident occurred on approach, landing, takeoff, departure, or within 3 miles of an airport)</i>			
Airport Name: <u>Sky Park</u> Airport Identifier: <u>18FD</u> Proximity to Airport: ☒ Off Airport/Airstrip ☐ On Airport/Airstrip ☐ N/A		Distance From Airport Center: <u>0.4</u> sm Direction From Airport: <u>280</u> degrees true Airport Elevation: <u>250</u> ft. msl	
Runway Information Runway ID: <u>09</u> (L/R/C) Length: <u>3000</u> ft Width: <u>200</u> ft		Condition of Runway/Landing Surface <i>(Check all that apply)</i> ☒ Dry ☐ Holes ☐ Ice Covered ☐ Rough ☐ Rubber Deposits ☐ Slush-Covered ☐ Snow-Compacted ☐ Snow-Crusted ☐ Snow-Dry ☐ Snow-Wet ☐ Soft ☒ Vegetation ☐ Water-Calm ☐ Water-Choppy ☐ Water-Glassy ☐ Wet ☐ Unknown	
Runway/Landing Surface <i>(Check all that apply)</i> ☐ Asphalt ☐ Concrete ☐ Dirt ☒ Grass/Turf ☐ Gravel ☐ Ice ☐ Macadam ☐ Metal/Wood ☐ Snow ☐ Water ☐ Unknown		Approach/Departure Segment <i>(Select one)</i> ☐ Taxi ☐ Takeoff ☐ Initial Climb ☐ VFR Departure ☐ IFR Departure Procedure/Clearance ☐ On Instrument Approach ☐ Landing ☐ Downwind ☐ Base ☐ Final ☐ Crosswind ☐ Low Approach ☐ Go Around ☐ Aborted Landing (after touchdown) ☐ Unknown	
IFR Approach <i>(Check all that apply)</i> ☒ None ☐ ADF/NDB ☐ SDF ☐ VOR/TVOR ☐ VOR/DME ☐ TACAN ☐ PAR ☐ Sideslip ☐ ILS ☐ Localizer Only ☐ LOC-back course ☐ RNAV ☐ MLS ☐ LDA ☐ ASR ☐ Visual ☐ Contact ☐ Circling ☐ Practice ☐ GPS ☐ Unknown		VFR Approach <i>(Check all that apply)</i> ☐ None ☒ Traffic Pattern ☐ Straight-In ☐ Valley/Terrain Following ☐ Go Around ☐ Full Stop ☐ Stop and Go ☐ Touch and Go ☐ Simulated Forced Landing ☒ Forced Landing ☐ Precautionary Landing ☐ Unknown	

“FLIGHT CREWMEMBER 1” INFORMATION

“Flight Crewmember 1” Responsibilities at the Time of Accident/Incident

☒ Pilot
 ☐ Co-Pilot
 ☐ Student Pilot
 ☐ Flight Instructor
 ☐ Check Pilot
 ☐ Flight Engineer
 ☐ Other Flight Crew

“Flight Crewmember 1” was pilot flying ☐ Yes ☐ No

“Flight Crewmember 1” Identification

First Name: Allan

City of Residence: Niceville

Middle Initial: G

State: FL ZIP: 32578

Last Name: Pixley

Country: USA

Age at time of Accident/Incident: 67 Date of Birth: mm/dd/yyyy

Certificate Number: mm/dd/yyyy

Degree of Injury

☐ None
 ☐ Fatal
 ☐ Minor
 ☐ Unknown
 ☒ Serious

Seat Occupied

☐ Left
 ☐ Front
 ☐ Unknown
 ☐ Right
 ☐ Rear
 ☒ Center
 ☐ Single

Restraint Type

Available

☐ None
 ☐ Lap only
 ☐ 3-point
 ☒ 4-point
 ☐ 5-point
 ☐ Unknown

Used

☐ None
 ☐ Lap only
 ☐ 3-point
 ☒ 4-point
 ☐ 5-point
 ☐ Unknown

Inflatable Restraints

☒ Not Installed
 ☐ Installed
 ☐ Not Deployed
 ☐ Deployed
 ☐ Unknown

Pilot Certificate(s) (Check all that apply)

☐ None
 ☐ Flight Instructor
 ☒ Commercial
 ☐ US Military
 ☒ Private
 ☐ Recreational
 ☐ Airline Transport
 ☐ Foreign
 ☐ Student
 ☐ Sport
 ☐ Flight Engineer

Principal Occupation

☐ Pilot
 ☒ Other
 ☐ Unknown

Medical Certificate

☐ None
 ☐ Class 3
 ☐ Class 1
 ☒ Driver's License (Sport Pilot only)
 ☐ Class 2
 ☐ Unknown

Medical Certificate Validity

☐ Without limitations/waivers
 ☐ Unknown
 ☐ With limitations/waivers
 ☒ N/A
 ☐ Special Issuance

Date of Last Medical

mm/dd/yyyy

Medical Certificate Limitations

N/A

Medical Certificate Special Issuance

N/A

Date of Last Flight Review or Equivalent, Including FAR 121/135 Checks:

07/10/2020
mm/dd/yyyy

Flight Review Aircraft

Make: Thatcher

Model: CX4

Airplane Rating(s) (Check all that apply)

☐ None
 ☒ Single-Engine Land
 ☐ Single-Engine Sea
 ☒ Multiengine Land
 ☐ Multiengine Sea

Other Aircraft Rating(s) (Check all that apply)

☒ None
 ☐ Airship
 ☐ Balloon
 ☐ Glider
 ☐ Gyroplane
 ☐ Helicopter
 ☐ Powered Lift

Instrument Rating(s) (Check all that apply)

☐ None
 ☒ Airplane
 ☐ Helicopter
 ☐ Powered Lift

Instructor Rating(s) (Check all that apply)

☒ None
 ☐ Instrument Airplane
 ☐ Airplane Single-Engine
 ☐ Instrument Helicopter
 ☐ Airplane Multi-Engine
 ☐ Helicopter
 ☐ Gyroplane
 ☐ Glider
 ☐ Powered Lift
 ☐ Sport

Type Ratings

None

Student Endorsements (Include dates)

N/A

Flight Time (Enter appropriate number of hours in each box)	All Aircraft	This Make & Model	Airplane Single Engine	Airplane Multiengine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time	1532.5	250.7	348	1184						
Pilot in Command (PIC)	1220	251	297.2	923						
Time as Instructor		0	0							
This Make/Model										
Last 90 Days	.2	.2	00	0						
Last 30 Days	0	0	0	0						
Last 24 Hours	0	0	0	0						

“FLIGHT CREWMEMBER 2” INFORMATION

“Flight Crewmember 2” Responsibilities at the Time of Accident/Incident

☐ Pilot
 ☐ Co-Pilot
 ☐ Student Pilot
 ☐ Flight Instructor
 ☐ Check Pilot
 ☐ Flight Engineer
 ☐ Other Flight Crew

“Flight Crewmember 2” was pilot flying ☐ Yes ☐ No

“Flight Crewmember 2” Identification

First Name: _____ City of Residence: _____
 Middle Initial: _____ State: _____ ZIP: _____
 Last Name: _____ Country: _____
 Age at time of Accident/Incident: _____ Date of Birth: _____ mm/dd/yyyy
 Certificate Number: _____

Degree of Injury

☐ None ☐ Fatal
☐ Minor ☐ Unknown
☐ Serious

Seat Occupied

☐ Left ☐ Front ☐ Unknown
☐ Right ☐ Rear
☐ Center ☐ Single

Restraint Type

Available

☐ None
☐ Lap only
☐ 3-point
☐ 4-point
☐ 5-point
☐ Unknown

Used

☐ None
☐ Lap only
☐ 3-point
☐ 4-point
☐ 5-point
☐ Unknown

Inflatable Restraints

☐ Not Installed
☐ Installed
☐ Not Deployed
☐ Deployed
☐ Unknown

Pilot Certificate(s) (Check all that apply)

☐ None ☐ Flight Instructor ☐ Commercial ☐ US Military
☐ Private ☐ Recreational ☐ Airline Transport ☐ Foreign
☐ Student ☐ Sport ☐ Flight Engineer

Principal Occupation

☐ Pilot
☐ Other
☐ Unknown

Medical Certificate

☐ None ☐ Class 3
☐ Class 1 ☐ Driver's License (Sport Pilot only)
☐ Class 2 ☐ Unknown

Medical Certificate Validity

☐ Without limitations/waivers ☐ Unknown
☐ With limitations/waivers ☐ N/A
☐ Special Issuance

Date of Last Medical

_____ mm/dd/yyyy

Medical Certificate Limitations

Medical Certificate Special Issuance

Date of Last Flight Review or Equivalent, Including FAR 121/135 Checks:

_____ mm/dd/yyyy

Flight Review Aircraft

Make: _____

Model: _____

Airplane Rating(s) (Check all that apply)

☐ None
☐ Single-Engine Land
☐ Single-Engine Sea
☐ Multiengine Land
☐ Multiengine Sea

Other Aircraft Rating(s) (Check all that apply)

☐ None
☐ Airship
☐ Balloon
☐ Glider
☐ Gyroplane
☐ Helicopter
☐ Powered Lift

Instrument Rating(s) (Check all that apply)

☐ None
☐ Airplane
☐ Helicopter
☐ Powered Lift

Instructor Rating(s) (Check all that apply)

☐ None ☐ Instrument Airplane
☐ Airplane Single-Engine ☐ Instrument Helicopter
☐ Airplane Multi-Engine ☐ Helicopter
☐ Gyroplane ☐ Glider
☐ Powered Lift ☐ Sport

Type Ratings

Student Endorsements (Include dates)

Flight Time (Enter appropriate number of hours in each box)	All Aircraft	This Make & Model	Airplane Single Engine	Airplane Multiengine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time										
Pilot in Command (PIC)										
Time as Instructor										
This Make/Model										
Last 90 Days										
Last 30 Days										
Last 24 Hours										

ADDITIONAL FLIGHT CREWMEMBERS (Exclusive of cabin crew, complete the following information)						
Crew Name and Address			Seat Occupied		Injury	
First Name: _____ City of Residence: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____			☐ Left ☐ Front ☐ Center ☐ Rear ☐ Right ☐ Single ☐ Unknown ☐ Unknown		☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Private ☐ Student ☐ Flight Instructor ☐ Recreational ☐ Sport ☐ Commercial ☐ Airline Transport ☐ Flight Engineer ☐ US Military ☐ Foreign			Restraint Type: Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		Inflatable Restraints ☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	
Type Rating/Endorsement for Accident/Incident Aircraft? ☐ Yes ☐ No		Total Flight Time at the Time of this Accident/Incident: _____ hrs				
Crew Name and Address			Seat Occupied		Injury	
First Name: _____ City of Residence: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____			☐ Left ☐ Front ☐ Center ☐ Rear ☐ Right ☐ Single ☐ Unknown ☐ Unknown		☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Private ☐ Student ☐ Flight Instructor ☐ Recreational ☐ Sport ☐ Commercial ☐ Airline Transport ☐ Flight Engineer ☐ US Military ☐ Foreign			Restraint Type: Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		Inflatable Restraints ☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	
Type Rating/Endorsement for Accident/Incident Aircraft? ☐ Yes ☐ No		Total Flight Time at the Time of this Accident/Incident: _____ hrs				
PASSENGER(S) / OTHER PERSONNEL (Include cabin crew; continue on separate sheet if necessary)						
Name and Address		Seat	Injury	Restraint Type		Inflatable Restraints
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other		☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown ☐ Under 5 years <i>If Under 5,</i> ☐ Child Restraint ☐ Lap-Held ☐ Unknown
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other		☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown ☐ Under 5 years <i>If Under 5,</i> ☐ Child Restraint ☐ Lap-Held ☐ Unknown
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other		☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown ☐ Under 5 years <i>If Under 5,</i> ☐ Child Restraint ☐ Lap-Held ☐ Unknown
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other		☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown ☐ Under 5 years <i>If Under 5,</i> ☐ Child Restraint ☐ Lap-Held ☐ Unknown

FLIGHT ITINERARY INFORMATION

Last Departure Point Airport ID: <u>18FD</u> City: <u>Baker</u> State: <u>Florida</u> Country: <u>USA</u>	Time of Departure Time: <u>0630</u> Time Zone: <u>Central</u>	Destination Airport ID: <u>18FD</u> City: <u>Baker</u> State: <u>Florida</u> Country: <u>USA</u>	Type Flight Plan Filed ☒ None ☐ VFR/IFR ☐ Company VFR ☐ IFR ☐ Military VFR ☐ Unknown ☐ VFR Activated? ☐ Yes ☐ No ☐ Unknown
--	--	---	--

Type of ATC Clearance/Service (Check all that apply)

☒ None	☐ Special VFR	☐ Special IFR	☐ VFR Flight Following	☐ Cruise
☐ VFR	☐ IFR	☐ VFR On Top	☐ Traffic Advisory	☐ Unknown / NA

Airspace where the accident/incident occurred (Check all that apply)

☐ Class A ☐ Class B ☐ Class C ☐ Class D ☐ Class E	☐ Class G ☐ Demo Area ☐ Warning Area ☐ Prohibited Area ☐ Restricted Area	☐ Military Operations Area (MOA) ☐ Airport Advisory Area ☐ Jet Training Area ☐ TRSA ☐ FAR 93	☐ Special ☐ Air Traffic Control Area ☐ Unknown	Altitude of In-Flight Occurrence: <u>900</u> ft msl
--	---	---	---	---

WEATHER INFORMATION AT THE ACCIDENT/INCIDENT SITE

Source of Pilot Weather Information

(Check all that apply)

☐ National Weather Service ☐ Flight Service Station ☐ TV/Radio ☐ Automated Report ☐ Commercial Weather Service (DUATS) ☐ On-Board Weather	☐ Company ☐ Military ☒ Internet ☐ None ☐ Unknown
--	--

Weather Observation Facility

Facility ID: _____
 Observation Time: _____
 Time Zone: _____
 Distance from Accident Site: _____ nm
 Direction from Accident Site: _____ degrees true

Basic Conditions

☒ VMC
☐ IMC
☐ Unknown

Light Condition

☒ Dawn ☐ Dusk ☐ Dark Night ☐ Unknown
☐ Day ☐ Night ☐ Bright Night

Sky/Lowest Cloud Condition

☐ Clear ☐ Thin Broken
☐ Few ☐ Thin Overcast
☐ Partial Obscuration ☐ Unknown
☒ Scattered

Lowest Cloud Condition Height

1500 ft agl

Ceiling

☐ None (Clear) ☐ Obscured
☒ Broken ☐ Indefinite
☐ Overcast ☐ Unknown

Ceiling Height

2500 ft agl

Temperature: _____ (C) or 73 (F)

Dew Point: _____ (C) or _____ (F)

Altimeter Setting: _____ in. Hg
or _____ MB

Wind Direction

☒ Variable

-or-
Direction: _____ degrees true

Wind Speed

☒ Calm
☐ Light and Variable

-or-
Speed: _____ kts

Wind Gusts

☒ Not Gusting

-or-
Speed: _____ kts

Visibility 10 miles

RVR: _____ feet

RVV: _____ miles

Density Altitude: _____ ft

Intensity of Precipitation

☐ Light
☐ Moderate
☐ Heavy
☒ N/A
☐ Unknown

Type of Precipitation (Check all that apply)

☒ None	☐ Drizzle	☐ Freezing Rain
☐ Rain	☐ Ice Pellets	☐ Snow Shower
☐ Snow	☐ Snow Pellets	☐ Ice Pellets Shower
☐ Hail	☐ Snow Grains	☐ Freezing Drizzle
☐ Rain Showers	☐ Ice Crystals	

Restriction to Visibility (Check all that apply)

☒ None	☐ Fog
☐ Blowing Dust	☐ Ground Fog
☐ Blowing Sand	☐ Haze
☐ Blowing Snow	☐ Ice Fog
☐ Blowing Spray	☐ Smoke
☐ Dust	☐ Unknown

Icing Forecast

Amount	Type
☒ None	☒ N/A
☐ Trace	☐ Rime
☐ Light	☐ Clear
☐ Moderate	☐ Mixed
☐ Severe	☐ Unknown
☐ Unknown	

Icing Actual

Amount	Type
☒ None	☒ N/A
☐ Trace	☐ Rime
☐ Light	☐ Clear
☐ Moderate	☐ Mixed
☐ Severe	☐ Unknown
☐ Unknown	

Turbulence

Type (Check all that apply)	Severity
☒ None	☐ Light
☐ Clear Air	☐ Moderate
☐ Terrain-Induced	☐ Severe
☐ Convective Turbulence	☐ Extreme

NOTAMs (D and FDC), AIRMETs, SIGMETs, PIREPs in effect at the time of the accident/incident:

DAMAGE TO AIRCRAFT AND OTHER PROPERTY

Aircraft Damage

- ☐ None ☐ Substantial
☐ Minor ☒ Destroyed
 ☐ Unknown

Aircraft Fire

- ☒ None ☐ Both Ground and In-Flight
☐ In-Flight ☐ Fire at Unknown Time
☐ On-Ground ☐ Unknown

Aircraft Explosion

- ☒ None ☐ Both Ground and In-Flight
☐ In-Flight ☐ Explosion at Unknown Time
☐ On-Ground ☐ Unknown

Description of Damage to Aircraft and Other Property *(Use additional sheet if necessary)*

Aircraft: Major structural damage to wings, fuselage, propeller, cockpit. No salvagable parts. Aircraft aluminum structure absorbed the brunt of remaining energy prior to final impact after loss of engine.

Property: Damage to the tree impacted, 2X2 area on ground killed grass from gas leak. The tree branch impacting power lines blew several transformers, repaired within 2 hours by Celco power company.

NARRATIVE HISTORY OF FLIGHT *(Please type or print in ink)*

Describe what occurred in chronological order, including circumstances leading to and nature of accident/incident. Describe terrain and include wreckage distribution sketch if pertinent. Attach extra sheets if needed. State departure time and location, services obtained, and intended destination. Provide as much detail as possible.

N347CX Accident on 16 July 22. The following is a narrative of actions and events leading up to the loss of N347CX.

I woke up at 0230 that morning. My plan was to drive the 45 minutes to my hangar in Baker, work on odd projects and conduct a first flight on my recently completed VW overhaul. On the drive to the hangar the window regulator in my car failed, so I pulled 347CX out of the hangar, put the car in and began working on it. After a few hours of work, the sun was up and I switched my focus to the early morning flight.

After being outside for three hours, the canopy was all fogged over and it took some effort to dry that off. I checked ForeFlight for the weather conditions at the surrounding airports and was surprised to see some reporting marginal IFR and some VFR. Baker looked scattered with good visibility. Since my plan was to takeoff, climb overhead and do engine break-in at 70%, WX was not a concern. Looking back, more attention to the high humidity and how it might impact flight ops might have helped.

Engine History: On last flights prior to overhaul, oil pressure dropped below spec value and in order to regain confidence in the motor, I made the decision to overhaul it. The process took almost 10 months due to parts and conflicting priorities. The first attempt resulted in the case leaking oil so I repeated the process and the second time got the Loctite 518 to seal correctly. Six ground runs were conducted during July chasing mag and secondary timing. Engine started on mid throttle setting, not idle. It was not until the last engine run that I got it to run smoothly in idle on both, single ignition sources (L/R). The day that test point occurred was after multiple runs and the oil was warm.

Preflight: The plane had almost full fuel (9.5/10.5g), preflight was normal, gascolator had no water in the fuel, and oil was full.

Engine start on was normal but hit a rough spot at one point on taxi and low RPM. That should have been a concern but I proceeded on because I figured it wasn't warmed up yet. Taxi distance from parking to RWY 09 was only 50' since my hangar is at the NW corner of the airfield. Mag check at 2500 RPM was less than 50 RPM.

Takeoff (0630) from RW09 was normal power/3400 RPM. Climb-out started my first distraction. Liquid started dripping on my legs and I immediately went to fuel leak. I've always had the plane indoors with exception of a few airshows and condensation never occurred to me. I tried to smell the fluid but the inside of that

plane smells like gas all the time so I made the decision to abort this flight until I could check it out. Potential fire in the cockpit overcame the number one risk which was owner overhauled engine and I flew a low pattern (900 vs 1200'). Next mistake was pulling power where I normally would at 1200', and then the motor stopped.

I honestly don't remember the exact sequence of engine restart and turn towards final. Did I do them together or were they two events? I don't know. I remember engaging the backup fuel pump and advancing the throttle to get the carb out of the idle circuit. I hit the starter twice, got nothing and made the decision it was time to just fly the airplane. Airspeed was 70 mph which was 10 mph too slow and the hardest thing I ever did was push forward. Stretched glide as far as I could knowing I was not going to make the field I was aiming for, just short of RW09. The Thatcher CX-4 doesn't really stall like most A/C, it does a controllable mush so I kept pulling back on the stick to stay above the trees.

As I came into the tree line on the edge of HWY 189, the left wing impacted a tree just above the power lines, absorbing energy and starting some rotation. The right wing impacted the ground next, followed by the nose into dirt. Aluminum from the leading edge of the left wing was found in the yard on the west side of HWY 189 and returned by neighbors. When I impacted the ground the cockpit was facing southwest and I remember watching the wires shake, transformers blow, and two of the four orange runway balls drop from the electrical

RECOMMENDATION (How could this accident/incident have been prevented?)

Operator/Owner Safety Recommendation

Throttle chops, as part of a thirty minute engine ground break-in process, may have discovered potential carburetor issue prior to first time flight.

MECHANICAL MALFUNCTION/FAILURE (If more space is needed, continue on separate sheet)

Was there Mechanical Malfunction/Failure? ☐ Yes ☒ No
(If yes, list the name of the part, manufacturer, part no., serial no., and describe the failure.)

**Total Time/Cycles
On Part**

_____ Hours

_____ Cycles

**Time Since This Part
Inspected/Overhauled**

_____ Hours

FUEL & SERVICES INFORMATION**Fuel on Board at Last Takeoff**

(Convert from pounds, as necessary)

9.5 Gallons**Fuel Type**☐ 80/87☐ 115/145☐ Jet B☒ Other, specify 93 Ethanol Free☐ 100 Low Lead☐ Jet A☐ JP8☐ 100/130☐ Jet A-1☐ Automotive**Other Services, if Any, Prior to Departure****EVACUATION OF AIRCRAFT****Was an emergency evacuation of the aircraft performed?** ☒ Yes ☐ No**Method of Exit** – Describe how the occupants exited and how many occupants evacuated each location

Bystanders who came to the scene assisted me out of the plane with a broken collarbone and knee injury.

OTHER AIRCRAFT – COLLISION (If air or ground collision occurred, complete this section for other aircraft)**Aircraft Registration Number**

Manufacturer: _____**Model:** _____**Damage to Other Aircraft**☐ Destroyed☐ Minor☐ Substantial☐ None**Registered Owner of Other Aircraft**

Name: _____

City: _____

State: _____ ZIP: _____

Country: _____

Pilot of Other Aircraft

Name: _____

City: _____

State: _____ ZIP: _____

Country: _____

ADDITIONAL INFORMATION (Please type or print in ink)

Use this space if additional space is needed for any answers.

I HEREBY CERTIFY THAT THE ABOVE INFORMATION IS COMPLETE AND ACCURATE TO THE BEST OF MY KNOWLEDGE

Date of this Report

07/21/2022

mm/dd/yyyy

Name of Pilot/Operator: Allan G. Pixley

Signature: _____

-- or -- ☒ Check here to electronically sign this document

If a Person Other than Pilot/Operator is Filing Report

Name: _____

Title: _____

Signature: _____

-- or -- ☐ Check here to electronically sign this document

FOR NTSB USE ONLY

NTSB Accident/Incident No.

ERA22LA323

Reviewed by NTSB Regional Office

AS-ERA

Name of Investigator

Lynn Spencer

Date Report Received

7/21/2022

N347CX Accident on 16 July 22. The following is a narrative of actions and events leading up to the loss of N347CX.

I woke up at 0230 that morning. My plan was to drive the 45 minutes to my hangar in Baker, work on odd projects and conduct a first flight on my recently completed VW overhaul. On the drive to the hangar the window regulator in my car failed, so I pulled 347CX out of the hangar, put the car in and began working on it. After a few hours of work, the sun was up and I switched my focus to the early morning flight.

After being outside for three hours, the canopy was all fogged over and it took some effort to dry that off. I checked ForeFlight for the weather conditions at the surrounding airports and was surprised to see some reporting marginal IFR and some VFR. Baker looked scattered with good visibility. Since my plan was to takeoff, climb overhead and do engine break-in at 70%, WX was not a concern. Looking back, more attention to the high humidity and how it might impact flight ops might have helped.

Engine History: On last flights prior to overhaul, oil pressure dropped below spec value and in order to regain confidence in the motor, I made the decision to overhaul it. The process took almost 10 months due to parts and conflicting priorities. The first attempt resulted in the case leaking oil so I repeated the process and the second time got the Loctite 518 to seal correctly. Six ground runs were conducted during July chasing mag and secondary timing. Engine started on mid throttle setting, not idle. It was not until the last engine run that I got it to run smoothly in idle on both, single ignition sources (L/R). The day that test point occurred was after multiple runs and the oil was warm.

Preflight: The plane had almost full fuel (9.5/10.5g), preflight was normal, gascolator had no water in the fuel, and oil was full.

Engine start on was normal but hit a rough spot at one point on taxi and low RPM. That should have been a concern but I proceeded on because I figured it wasn't warmed up yet. Taxi distance from parking to RWY 09 was only 50' since my hangar is at the NW corner of the airfield. Mag check at 2500 RPM was less than 50 RPM.

Takeoff (0630) from RW09 was normal power/3400 RPM. Climb-out started my first distraction. Liquid started dripping on my legs and I immediately went to fuel leak. I've always had the plane indoors with exception of a few airshows and condensation never occurred to me. I tried to smell the fluid but the inside of that

plane smells like gas all the time so I made the decision to abort this flight until I could check it out. Potential fire in the cockpit overcame the number one risk which was owner overhauled engine and I flew a low pattern (900 vs 1200'). Next mistake was pulling power where I normally would at 1200', and then the motor stopped.

I honestly don't remember the exact sequence of engine restart and turn towards final. Did I do them together or were they two events? I don't know. I remember engaging the backup fuel pump and advancing the throttle to get the carb out of the idle circuit. I hit the starter twice, got nothing and made the decision it was time to just fly the airplane. Airspeed was 70 mph which was 10 mph too slow and the hardest thing I ever did was push forward. Stretched glide as far as I could knowing I was not going to make the field I was aiming for, just short of RW09. The Thatcher CX-4 doesn't really stall like most A/C, it does a controllable mush so I kept pulling back on the stick to stay above the trees.

As I came into the tree line on the edge of HWY 189, the left wing impacted a tree just above the power lines, absorbing energy and starting some rotation. The right wing impacted the ground next, followed by the nose into dirt. Aluminum from the leading edge of the left wing was found in the yard on the west side of HWY 189 and returned by neighbors. When I impacted the ground the cockpit was facing southwest and I remember watching the wires shake, transformers blow, and two of the four orange runway balls drop from the electrical wires.

There were Angles flying with me that morning. With a broken collarbone and deep lacerations to one knee, I could not get out of the plane. Fortunately there were vacation travelers heading home who stopped, pulled me out, and called 911.

Allan G. Pixley