



MEMORANDUM FOR RECORD

Eric Alleyne
Air Safety Investigator
National Transportation Safety Board
Office of Aviation Safety - Eastern
Region

NTSB Case Number: ERA22LA330
Model/N#: Bell 206B/ N39MK
Date: 9/2/2022
FAA inspector: Joseph W. Korecz
Subject: Examination of fuel system
and engine

This email was discussed during a telephone interview with inspector Korecz. The inspector that conducted the examination of the engine and the helicopter did not find any anomalies that have precluded normal operation.

"On September 2, 2022 N39MK was located at the Hartselle/Morgan county Regional airport, 450 Airport RD SW Hartselle, Alabama 35640 phone number 256-773-1130. An inspection of the fuel tank (cell) and engine was conducted by a FAA inspector, ASI Clay Perkins from the Birmingham FSDO 205-876-1316. A visual inspection of the fuel tank (cell) was conducted by the inspector and found to be intact but the fuel tank (cell) was empty of fuel. An picture of the interior fuel tank is attached to this email. A visual inspection of the engine was conducted and found to be intact. Pictures of the engine are attached to this email. Please contact me if you have any questions."