



Photo 1 – View of tail section of helicopter damaged (FAA Photo)



Photo 2 – View of inside fuel cell revealing empty fuel cell (FAA Photo)