

N42WC

10/27/2021

S/N 1531M

Hobbs: 2171.50/AFTT: 6584.71

CW AD 2011-12-10 by inspecting the Main rotor blades I/A/W RHC and AD instructions. Replaced the paper air filter with a new A771-1. Patched float valves on the left float in Bays 1 & 3, and the right float bay 2. replaced 1 of the TRPL with a serviceable B345-3 TRPL. Replaced the Com/Gps Antenna with a serviceable used CI-2480-201 Gps/Com Antenna. CW AD 88-26-01r2 by removing the Main rotor blades and inspecting the spindles I/A/W RHC and AD instructions, reinstalled blades and balanced to 0.09 Ips. Next due by AFTT: 7058.4 All work done I/A/W RHC M/M. I certify that this acft has been inspected I/A/W a 100hr/Annual inspection as set forth by part 43, Appendix D. and has been found to be in an airworthy condition and fit to return to service---
-----end-----

Forrest Santos

N42WC

07/02/2021

S/N L-16576-39A

Hobbs: 2171.50/ETSMOH: 6584.71

Engine compressions as follows, #1 72/80, #2 76/80, #3 75/80, and #4 73/80. Removed, Cleaned, Inspected, and reinstalled all spark plugs in a rotated order Drained oil, cleaned screen, replaced the filter with a CH48018-1 oil filter, and serviced with 6 qts Phillips 20w50XC. Inspected this engine I/A/W a 100hr./Annual inspection as set forth by part 43, Appendix D-----
-----end-----

Forrest Santos