



NTSB MEMORANDUM OF RECORD

Lynn Spencer
Air Safety Investigator
Eastern Region, Office of Aviation Safety (AS-ERA)
National Transportation Safety Board

NTSB Accident Number: ERA22LA348
Subject: CASA 212 Measurements and Photo
Date: 10/14/2022

On October 14, 2022, at 751 EDT, I made an email request to the operator for the following measurements:

1. Distance between the cockpit threshold and the far edge of the ramp (the edge they jump from) when the ramp is set at "level" for the jumpers
2. Distance between the cockpit threshold and the near end of the ramp (i.e. where the drop-off would begin when the ramp is fully lowered)

I also requested a photo from the left cockpit seat looking back with the ramp fully lowered (or as low as it could be while the aircraft was on the ground), so that the floor of the cabin was visible.

The e-mail response was received on October 14, 2022, at 1214 EDT. The below measurements and photo were included:

- Distance from cockpit bulkhead to end of ramp door: 25' 10"
- Distance from cockpit bulkhead to the pivot point of ramp door: 21' 5 3/4"




NTSB MEMORANDUM OF RECORD



Photo 1- Photo looking from cockpit aft to rear of airplane with ramp open (Photo courtesy of Rampart Aviation)

Measurement 1: cockpit to ramp end when ramp is level



Measurement 2: cockpit to ramp forward edge when fully down