

FORMED—
PERFORMING WORK

N500JG
PA-32-300
S/N: 32-40726

Reinstalled upon

(ii) and service kit

12-4-2 rivets.
12-4-2 rivets.
talled and bolt and

5094 IA

IN: TN 37172

ber 07, 2021

the scope and
ance manual

talled (1) BP-

struments,

nth or 110

. Next due

c). Next due

d in view of

an Annual

615-364-3200

2021

DESCRIPTION OF WORK PERFORMED—
SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK

DATE TOTAL
TIME IN
SERVICE TACH OR
RECORDING
METER
TIME

Airframe - page 1 of 2

wo: 22-1306

Wingnuts Aviation, LLC - Mailing Address, [REDACTED] Clarksville, TN 37043 Facility Address, [REDACTED]
[REDACTED] Springfield, TN 37172 [REDACTED]

N500JG
TACH: 3623.3

Piper, PA-32-300, S/N: 32-40726

October 04, 2022

1. Complied with an Annual Inspection in accordance with out checklist encompassing the scope and detail of 14CFR (FAR) 43 appendix D with reference to the Piper Cherokee Six maintenance manual and all applicable ICA's.
2. Researched AD's through bi-weekly 2022-20 and found to be in compliance.
3. Tested ELT IAW FAR 91.207(d). Battery expires 09/30/23.
4. Complied with AD 70-26-04 [R2] Weight Tube by dye penetrant inspection IAW Section III. Next due 200 hours.
5. Complied with AD 75-24-02 Loose Seats by visual and operational inspection IAW (1)(2). Next due 12 months.
6. Complied with AD 76-07-12 Ignition Switches by operational inspection IAW steps (a)(b)(c). Next due 12 months or 100 hours.
7. Complied with AD 77-12-01 Fuel System by functional test IAW paragraph (a). Next due 50 hours.
8. Complied with AD 78-23-01 Fuel Drain Doors Assembly IAW paragraph (b). Next due 100 hours.
9. Complied with AD 13-02-13 Control Cables by visual inspection IAW paragraph g. Next due 7 years or 2000 hours.
10. Complied with AD 15-19-07 Fuel Lines by visual inspection IAW (e)(ii). Next due 12 months or 110 hours.
11. Replaced induction air filter element. Installed P/N BA3 - Filter; Induction Air.
12. Replaced vacuum pump with overhauled from Aero Accessories, WO IOYA8-0000. Installed P/N 215CC OH - Pump; Dry Air (Overhauled) S/N: OYA804, Installed P/N 61183 - Gasket, Accessory Adapter.
13. Replaced cylinder 6 JPI CHT probe. Installed P/N 5050 SVC - Probe; CHT (Serviceable).
14. Replaced both main tires with overhauled from Wilkerson Company, Inc., WO 44623170 and new tubes. Installed (2) P/N TU 15/600-6 GY - 15/600-6 Goodyear Flight Mate Tube (TR-20 Valve). Installed (2) P/N 600-6 6ply RT - 600-6 6 PLY High Performance Retread Aircraft Tire.
15. Replaced nose tire and tube with new. Installed P/N TU 15/600-6 GY - 15/600-6 Goodyear Flight Mate Tube (TR-20 Valve). Installed P/N 600-6 8ply GY2 - 600-6 8 PLY Goodyear Flight Special II. Aircraft Tire.
16. Installed cockpit sunvisors from Rosen Sunvisor Systems, LLC in accordance with FAA approved Rosen Drawing List Number RPF-00DL, Revision C, dated March 3, 2005 and STC SA00072SE.

I certify that this Aircraft has been inspected in accordance with an Annual Inspection and was determined to be in airworthy condition.

David Bliss AP / IA [REDACTED]

SUB-TOTAL this page

TOTAL—Carry forward to next page