



Ralph E. Hicks
Senior Air Safety Investigator
AS-ERA

Date: 2/16/2024

Subject: ERA23FA070, Correspondence with TT&WN Director of
Maintenance

Mr. James Keating, the operator's (TT&WN) Director of Maintenance confirmed that the left forward control rod end to the stationary swashplate (Robinson Helicopter Company part number D 173-1), along with the other two adjacent upper rod ends were replaced during the field overhaul of August 15, 2019. The lower rod ends were also replaced during that overhaul.