



Eric Alleyne
Air Safety Investigator
AS- Eastern Region Aviation

Date: 3/5/2023

Subject: ERA23FA136, fuel selector operation discussion

Contact: Brain Morford, STC holder, Dakota Cub Aircraft

The information below was discussed with Mr. Morford regarding the position of the fuel selector.

During a discussion with Mr. Morford of Dakota Cub Aircraft, he stated that if the fuel selector is in the 45° position the fuel will shut off. In the positions between the definitive tank selection the fuel flow is limited. He also said that test the flow with air is not a proper measure to test the selector, because air will seep thru.

-END-