



Eric Alleyne
Air Safety Investigator
AS-Eastern Region Aviation

Date: March 6, 2023

Subject: ERA23FA136, photo review

Contact: Fannin County Sheriff's Office

This photograph was obtained from the Fannin County Sheriff's Office before the removal of the pilot. It clearly shows the fuel selector handle was positioned between the both and right fuel tank. During the on-scene investigation, the position of the selector was confirmed. Subsequently, the selector was carefully removed for a detailed examination. The inspection revealed no irregularities or issues, confirming that the selector was functioning properly and would not have hindered normal operation.



Photo of fuel Selector