



Memorandum For Record

Timothy W. Monville
Sr. Air Safety Investigator
Eastern Region

Date: 10/11/2023
NTSB Accident Number: ERA23FA138

As part of the investigation, video files from the airport depicting the approach, go-around or accident sequence, some with sound were provided to NTSB. The video files were provided to the NTSB Vehicle Recorder Division for analysis. Information about the camera locations follows:

Camera 1: Mounted on a soffit 8 ft 7 inches above ground level at Palm Beach Copters building at 26.588764° north and -080.084535° west. The camera had east and south views and sound. Video GLEU2498.

Camera 2: Mounted on a soffit 8 ft 7 inches above ground level at Palm Beach Copters building at 26.588779° north and -080.084556° west. The camera had north and west views and sound. Video YGQC7749.

Camera 3: Mounted on a soffit 9 ft 1 inches above ground level at 26.588761° north and -080.084155° west. The camera had north and east views but no sound. Video YIKR9654.

Two witnesses who were on the ramp at the accident airport and whom witnessed the approach, go-around, and accident sequence also provided NTSB videos, with sound, that were provided to the NTSB Vehicle Recorder Division for analysis. The witnesses were located at 26.589712°N latitude and -080.083888°W longitude. One witness (West) provided videos identified as IMG_4101; IMG_4102; IMG_4103; and IMG_4106. The second witness (a minor) provided NTSB video file IMG_2078 which contained sound and the final portion of the flight.