



Memorandum For Record

Timothy W. Monville
Sr. Air Safety Investigator
Eastern Region

Date: 10/11/2023
NTSB Accident Number: ERA23FA138

As part of the investigation in an effort to locate the separated throttle cable rod end, Detective R. Rohman of Palm Beach County Sheriff's Office (PBSO) was contacted to see if they had a metal detector to examine the resting area of the engine.

On April 16, 2023, at 1558 EDT, Sergeant Jarry Lamm of PBSO sent an e-mail to NTSB advising, "Good afternoon Tim, I wanted to let you know on Saturday, April 15, 2023 I met with our crime scene at the plane crash site in Lantana, FL and we attempted to locate the missing part you sent us via email. We ran metal detectors over the entire plane crash incident location and we did not discover any metal debris in the area. I will document this in our PBSO Case file as a supplement report."