



MEMORANDUM FOR RECORD

Aaron McCarter
Aviation Accident Investigator
Eastern Region Aviation

Date: April 26, 2023
NTSB Accident Number: ERA23FA185

Medical and Pathological Information:

An autopsy of the pilot was performed by the Medical Examiner Department, District 19, St. Lucie, Martin, Indian River and Okeechobee Counties, Florida. The pilot's cause of death was multiple blunt force injuries and manner of death was an accident.

Toxicology testing performed by the FAA's Forensic Services Laboratory in Oklahoma City on the pilot's blood and urine did not detect any substance that would be considered impairing. Additional testing was conducted postmortem by Steward Reference Laboratory of Melbourne, Florida and was negative for alcohol and illicit substances.