



Investigator Name: Leah D. Read
Title: Sr. ASI
Division: ERA

Date: May 6, 2025

Subject: ERA23FA235

Contact: Thomas Sully, Air Safety Investigator, HondaJet

On May 6, 2025, Mr. Thomas Sully, on behalf of HondaJet, stated via writing, that HondaJet granted the NTSB permission to release HondaJet Service Bulletin SB-420-42-019 (Rev C) and Service Letter SL-420-42-011, into the NTSB public docket for accident investigation ERA23FA235, "...as they promote the safe operation of the aircraft."

Both the Service Bulletin and the Service Letter had the below disclaimer:

"The information and design disclosed herein was originated by and is the property of Honda Aircraft Company, LLC who reserves all patent, proprietary, design, manufacturing, reproduction, use and sale rights thereto, and to any article disclosed herein except to the extent rights are granted in writing to others by an authorized official of Honda Aircraft Company, LLC. The foregoing does not apply to proprietary articles and/or designs of others."