



Aeroworx, LLC
4015 airport rd W1
Southport NC 28465
910-933-6159

Invoice #: 1021
Inv. Date: 10/13/2022
Terms:
Written By: William Philbrick

Customer: Luke Lucarelli Address: [REDACTED] North Myrtle Beach SC 29579-5845 Phone: [REDACTED]		Aircraft: Mooney M20R Tail #: N13LV S/N: 29-0152	
TTAF:	Tach:	TTE:	TTP:
		HOBBS:	Misc Time:

	Hours	Per Hour	Total
Labor/Repair	23.00	90.00	2070.00
serviced and bled brakes, attached standby vacuum pump hose to regulator, replaced rocker cover gaskets, bead blasted and painted rocker covers, trouble shot interior lights.			
removed no.2 and no.6 cylinders replaced exhaust studs on no.2 and no.6 cylinders installed crlinders	27.00	90.00	2430.00
strip and paint top half of fuselage and cowling	41.00	90.00	3690.00
put N number on	2.00	90.00	180.00

	Qty	Cost	Total
Parts			
hydraulic fluid 5606	1.00	11.21	11.21
630286 seal O-ring	4.00	5.35	21.40
534610 push rod seal	4.00	1.65	6.60
630979-9 O-ring	2.00	3.25	6.50
641066 O-ring cylinder base	8.00	10.50	84.00
633958-2 seal comp	2.00	6.45	12.90
657985-1-38 stud	8.00	13.40	107.20
10-32 scrow	30.00	0.19	5.70
no.10 nylon washer	30.00	0.05	1.50
aircraft paint remover	1.00	350.75	350.75
vinyl N number	2.00	100.00	200.00

Description	Cost
shop supplies	50.00
wash pimer, primer, paint, reducer, hardner	1000.00
This aircraft is unairworthy at this time	0.00

Labor Total:	\$8370.00
Part Total:	\$807.76
Misc Total:	\$1050.00
Sales Tax (6.7500%):	\$54.52
Shipping:	\$0.00
Fuel:	\$0.00
Total:	\$10282.28