



Joshua Young
Air Safety Investigator
AS-ERA

Date: 4/22/2024

Subject: ERA23FA313, Fuel amount at tabs

Contact: Kris Wetherell, Air Safety Investigator, Piper Aircraft

Mr. Wetherell was emailed and asked to verify the amount of fuel aboard a Piper PA-28R-200 if the wing fuel tanks had been filled "to the tabs." He responded and stated the following:

"It is 18 gallons per side to the tabs on the Arrow."