

 DEPARTMENT OF TRANSPORTATION FEDERAL AVIATION ADMINISTRATION REPORT OF AIRCRAFT ACCIDENT (Continuation Sheet)	REPORT DATE September 25, 2023	REPORT NO. 23-002-PMP-FCT
	NAME OF REPORTING FACILITY Pompano Beach FCT (PMP)	

14. CHRONOLOGICAL SUMMARY OF FLIGHT
August 28, 2023

ALL TIMES BELOW ARE COORDINATED UNIVERSAL TIME
UNLESS OTHERWISE SPECIFIED

1242 Pompano Tower (PMP) Ground Control (GC) is combined into Local Control (LC). BS09, a Broward Sheriffs Office Eurocopter (EC135), called LC from Spot 3 requesting westbound departure. LC provided current wind and altimeter then LC asked BS09 if he wanted to go direct. BS09 responded to LC stating he could depart direct on Taxiway Lima. LC cleared BS09 for takeoff on Taxiway Lima and crossing Runway 24. LC provided BS09 a frequency change west of field. BS09 acknowledged.

1243 BS09 called LC advising engine failure, requesting priority, and declaring an emergency. LC cleared BS09 to land Runway 6. BS09 acknowledged.

1244 LC called 911 after observing BS09 go down half a mile Southwest of field.

No More Follows