

Ralph E. Hicks
Senior Air Safety Investigator
AS-ERA

Date: 11/15/2022

Subject: ERA23LA011, NTSB IIC Interview with Left Rear Seat Passenger
John Meyer [REDACTED]

Mr. Meyer was interviewed by phone and reported the following:

- Mr. Meyer's full legal name is John Christopher Meyer II. DOB [REDACTED]
- Mr. Meyer's written statement was reviewed and he had no additional information to add.
- Mr. Meyer described his injuries. He sustained broken sternum and some broken ribs. He had 2 front teeth knocked out. Injury to AC joint and collarbone....seeing surgeon next week. Hematoma and partial tear to one pectoral muscle.
- He was treated at Gulf Coast Medical Center, as were the other 3 occupants of the helicopter.
- He has had follow-up treatment and will forward their contact information.
- He stated that he was strapped into his seat in a "normal" manner.