



Ralph E. Hicks
Senior Air Safety Investigator
AS-ERA

Date: 10/9/2022

Subject: ERA23LA011, Local Area Weather Observations

METAR KFMY 082153Z 06011KT 10SM BKN040 29/21 A3001 RMK ZMAFD
(FMY was located about 6 nm NE of accident site)

METAR KRSW 082153Z 05010KT 10SM OVC039 28/21 A3001 RMK AO2 SLP160 T02780206
(RSW was located about 10 nm ENE of the accident site)