



Photo 1 – View of helicopter resting on right side showing damage to main rotors and tail boom.



Photo 2 – View of aft of helicopter resting right side showing buckled tail boom.