



Heidi Kemner
Senior Air Safety Investigator
Aviation Safety - Eastern Region

Date: January 23, 2023
Subject: ERA23LA044
Contact: Kevin David - FSDO Inspector

In an email, Inspector David stated the following:

I could not tell what caused the dent in the tail rotor blades either, there was no signs of bird on them. The flight controls that were moved correctly for the ones that were connected.