



Christopher Freeze
Air Safety Investigator
Office of Aviation Safety - Eastern Region

Date: December 19, 2022
Subject: ERA23LA061
Contact: Pat Rooney
Owner of Piper Warrior, N6303J
Phone: [REDACTED]

On Monday, December 19, 2022, at 3:30 p.m., I spoke with - via phone - Pat Rooney, the owner of the Piper airplane, registered as N6303J, involved in the accident on November 14, 2022.

He stated that he was the person that, after the accident, informed the flight instructor that the airplane's fuel tank selector was in the 'off' position.