



Ralph E. Hicks
Senior Air Safety Investigator
AS-ERA

Date: 5/10/2023

Subject: ERA23LA064, Correspondence with Pilot Mutaz Al Sajee

During a telephone interview with Mr. Al Sajee on January 12, 2023, he reported that the accident airplane had been flown since the 25th of October 2022 with both red alternator warning lights illuminated continuously.

He provided photos via email that he took in flight on October 28, 2022 showing the aircraft in operation in flight with both alternator lights illuminated.




Photo 1: iPhone Photo taken on October 28, 2022 showing both alternator lights illuminated (left, center of photo).