



Aaron McCarter
Aviation Accident Investigator
Eastern Region

Date: November 23, 2022 through January 19, 2023

Subject: ERA23LA065: Attempts to get operators 6120 accident report.

Contact: Director of Safety and CP; Doug Yurovich @ [REDACTED]

The NTSB IIC (McCarter) made numerous requests to the operator to get a completed 6120 accident report. Several phone calls and e-mail request were made by the IIC, and each request was acknowledged, but no report was received.

November 23, 2022: Phone call with Mr. Yurovich and subsequently sent via e-mail a 6120 accident report which was immediately acknowledged stating he was "In work,"

December 2, 2022: Received the insurance loss report from Mr. Yurovich via e-mail.

December 12, 2022: NTSB e-mailed Mr. Yurovich asking if he had sent the accident report as discussed.

December 14, 2022: Mr. Yurovich responded by e-mail "No, I did not. Will complete." Which was acknowledged by the IIC.

January 19, 2023: The IIC e-mailed another copy of the 6120 report to Mr. Yurovich and asked for engine and airframe maintenance records, pilot information and mechanic information. And made another request for the 6120. This was immediately responded to, stating that "I no longer have the maintenance information." I will complete the rest of the 6120 and send it soonest.

There were no further communications from Mr. Yurovich. [END]