




Photo 1 – Last Condition Inspection (FAA)

YEAR 20 <u>22</u> DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
19-OCT	746.4		120.4	Conducted 25 hr Service check per RHMC Mx Manual. Oil and Filter Replaced. Added 5Q+5 valvoline VR-1 20W-50. Added 1 PT Avblend. Valve lash checked and adjusted for all cylinders. Main drive belts cleaned with acetone. Checked all hose clamps. Retorqued exhaust bolts. Aircraft OK to return to Service. [REDACTED]
11-Nov-22	755.2			[REDACTED]

YEAR
20 _____
DATE

Photo 2 – RHMC 25 hr Service Check (FAA)