

NTSB ERA23LA104

N2354E, Cessna 172

Photo Array



Photo 1: Overview of the left wing and substantial damage (Photo Courtesy of FAA)



Photo 2: Additional view of the substantial damage sustained to the left wing (Photo Courtesy of FAA)



Photo 3: View of the propeller damage (Photo Courtesy of FAA)



Photo 4: View of the Convair C-131F (Photo Courtesy of the Airport Operations)